

# DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS AND MINING

1594 West North Temple, Suite 1210 Michael O. Leavitt PO Box 145801 Governor

Salt Lake City, Utah 84114-5801 Kathleen Clarke 801-538-5340 **Executive Director** 

801-359-3940 (Fax) Lowell P. Braxton 801-538-7223 (TDD) Division Director

Existing Acreage: Permitted 5179.49

Status: Active XXX

## INS

Inspection Date & Time: 01/31/01 /8:30-10:30 AM

Regraded

INSPECTIO	N REPORT	
Complete:	Exploration:	_

Seeded

Division Director ■ 801-538-7223 (TDD)	Date of Last Inspection: 12/22/2000			
	nty: <u>Carbon</u>	Permit Number:	Carles 9	
Permittee and/or Operator's Name:Andal	ex Resources, Inc.		<del></del>	
Business Address: P.O. Box 902, Price, Ut	ah 84501			
Type of Mining Activity: Underground XX	XX Surface	Prep. Plant	Other	
Company Official(s): Mr. Mike Glasson, Se	enior Geologist			
State Official(s): Peter Hess Federal Offi	cial(s): None			
Weather Conditions: Clear, cold; teens Fahr	enheit; mild breezes			

Partial: XXX

# REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

Disturbed 35.27

- Substantiate the elements on this inspection by checking the appropriate performance standard.
  - a. For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
  - For partial inspections check only the elements evaluated.
- Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
- Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

		EVALUATE <u>D</u>	<u>N/A</u>	COMMENTS	NOV/ENE
1.	PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	[X]		[X]	П
2.	SIGNS AND MARKERS	[X]	$\Box$	<u>∐</u> .	$\Box$
3.	TOPSOIL	[X]	$\Box$		$\Box$
4.	HYDROLOGIC BALANCE:				
	a. DIVERSIONS	[X]	$\Box$	M	$\Box$
	b. SEDIMENT PONDS AND IMPOUNDMENTS	[X]			$\Box$
	c. OTHER SEDIMENT CONTROL MEASURES	$\Box$	Ц	· 📙	$\Box$
	d. WATER MONITORING	[X]	$\Box$	[X]	$\Box$
	e. EFFLUENT LIMITATIONS	$\Box$	$\Box$		
5.	EXPLOSIVES		$\Box$	$\Box$	$\Box$
6.	DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	· [_]	[X]	$\Box$	
7.	COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	$\Box$	[X]	$\Box$	$\Box$
8.	NONCOAL WASTE	[X]	П	[X]	$\Box$
9.	PROTECTION OF FISH, WILDLIFE AND RELATED				
	ENVIRONMENTAL ISSUES	$\Box$	$\Box$	$\Box$	
10.	SLIDES AND OTHER DAMAGE	$\Box$	[X]		$\Box$
11.	CONTEMPORANEOUS RECLAMATION		[X]	$\Box$	
12.	BACKFILLING AND GRADING		[X]		$\Box$
13.	REVEGETATION	$\Box$	[X]	$\Box$	
14.	SUBSIDENCE CONTROL		$\Box$	$\Box$	$\Box$
15.	CESSATION OF OPERATIONS	$\Box$	$\Box$	$\Box$	$\Box$
16.	ROADS:				
	a. CONSTRUCTION/MAINTENANCE/SURFACING	$\Box$	$\Box$	$\Box$	$\Box$
	b. DRAINAGE CONTROLS	$\Box$	$\Box$		
17.	OTHER TRANSPORTATION FACILITIES	[X]	$\Box$	$\Box$	$\Box$
18.	SUPPORT FACILITIES/UTILITY INSTALLATIONS	[X]	П	$\Box$	. [ <u>]</u>
19.	AVS CHECK (4th Quarter- April, May, June)	$\Box$	$\Box$		$\Box$
20.	AIR QUALITY PERMIT		$\Box$		
21	PONIDING & INCLIDANCE	Γ٦	f 1	[1	[1

#### INSPECTION REPORT

(Continuation sheet)

PERMIT NUMBER: C/007/019

DATE OF INSPECTION: 1/31/2001

#### ( COMMENTS ARE NUMBERED TO CORRESPOND WITH TOPICS LISTED ABOVE )

Note: Much of the site is covered with frozen, compacted snow. Some drifting has occurred due to high winds which have been experienced in the Deadman Canyon area this week.

The permittee anticipates that the resumption of coal production will take place in the Pinnacle Mine (one continuous miner section in the Centennial seam) on or about April 1, 2001.

### 1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE

Negotiations between Mr. Dan Guy, PE, of Blackhawk Engineering, and the UDNR/OGM/SLO continue relative to the determination of adequate bond amount. This is part of the midterm permit review for the Centennial site.

#### 4A. HYDROLOGIC BALANCE: DIVERSIONS

The majority of the site's diversions are buried and not capable of being inspected.

#### 4D. HYDROLOGIC BALANCE: WATER MONITORING

The permittee has not, to date, performed the required water monitoring/sampling for the first quarter of 2001 for the Centennial site. Ms. Karla Knoop performs the field sampling for the Centennial site as well as the West Ridge Mine and Wildcat Loadout sites.

The permittee has not submitted the fourth quarter 2000 water monitoring information for the Centennial site as of today's inspection.

As noted in the December 2000 inspection report, a determination that there was missing water monitoring information for Well #1 for the second and fourth quarters of 1999 existed. A second request was made to Mr. Glasson to provide that missing information.

# 8. NONCOAL WASTE

The permittee has removed the empty drums which contained the two component "ROK-LOK" chemicals from the site.

Inspector's Signature:

Peter Hess #46

Date: <u>January 31, 2001</u>

Note:

This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas & Mining.

sd

cc:

James Fulton, OSM Mike Glasson, Andalex

Price Field office

O:\007019.CEN\Compliance\2001\p 0131.wpd